

# FATALGRAM

## FATALGRAM 24-02

Alaska Department of Labor & Workforce Development  
Division of Labor & Safety Standards  
Occupational Safety & Health



**Date of incident:** May 18, 2024  
**Industry:** Oil and Gas Production  
**Location:** Milne Point, Alaska

**Summary:** An employee was struck and killed by a loader while walking on a job site.

**Description of Accident:** A 62-year-old male sustained crushing injuries from being struck by a front-end loader while walking to move a truck on a job site. First responders were immediately called to the scene, but efforts to revive him were unsuccessful.

### Accident Prevention Recommendations:

- Ensure employees who are exposed to equipment traffic wear hi-visibility outer wear that meets applicable ANSI or MUTCD standards.
- Ensure that employees are adequately trained to recognize and avoid unsafe conditions regarding loading and unloading materials involving heavy machinery, transport vehicles, and pedestrians.
- Ensure employees never cross the path of operating equipment without obtaining positive acknowledgement from the operator, i.e. eye contact.
- Establish and implement a safety and health program consisting of daily efforts to demonstrate management commitment and employee involvement, worksite analysis, hazard prevention and control, and safety and health training.